#### TRANSWESTERN PIPELINE COMPANY

# GAS SAMPLING RESULTS (Reference EPA Letter 12/7/81)

## July 15, 1982

SAMPLING LOCATION Pacific Lighting

DATE OF SAMPLING 6-8-82

SAMPLE NUMBER 82-P - 466

SAMPLE VOLUME 50 liters

ANALYTICAL RESULT 16.3 ug/m<sup>3</sup>

LIMIT OF DETECTION 0.2 ug/m<sup>3</sup>

COMMENTS 
BLANK RESULT 44 ng

ASSOCIATED CONDENSATE SAMPLING RESULT

89 ppm

#### TRANSWESTERN PIPELINE COMPANY

## MONITORING CONDENSATE SAMPLING RESULTS

(Reference EPA Letter 12/7/81)

July 15, 1982

Location	Station Name	Sampling Date Number		Results (PPM)*	Comments
(Distribution supply location	on a section of system which is not	contaminated)			•
Hemphill County, Texas	Cities Service - Canadian	6-29-82	464	1	
(Point on contaminated portion	n of the system where gas is supplie	d to another tra	nsmission com	pany)	
Needles, Arizona	Pacific Lighting	6-14-82	440	89	
		•			
(Collection point within the	contaminated portion of system where	large volumes o	f condensate	are normally found)	
Flagstaff, Arizona	Compressor Sta. #2	6-15-82	428	90	
Thoreau, New Mexico	Compressor Sta. #5	6-28-82	450	158	
Mountainair, New Mexico	Compressor Sta. #7	5-21-82	368	38	
	-				

<sup>\*</sup>Analysis - Texas Eastern Analytical Laboratory Analytical Aroclor 1242

4.

#### TRANSWESTERN PIPELINE COMPANY

### CONDENSATE COLLECTION REPORT

(Reference EPA Letter 12/7/81)

DATE OF REPORT July 1, 1982

FOR PERIOD April 1, 1982 TO July 1, 1982

Location	Date of Collection	Volume Collected	PCB Concentration	Date of Last Sample	Liquid Stored	Liquid Disposed of By
Cities Service - Canadian	4-1-82	73206 gals.	LY 1	6-29-82	Canadian, TX	
Pacific Lighting - Needles	6-30-82	233 gals.	89	6-14-82	Needles, AZ	
Flagstaff Compressor Sta.	6-30-82	7400 gals.	90	6-15-82	Flagstaff, AZ	•
Thoreau Compressor Sta.	6-30-82	9625 gals.	158	6-28-82	Thoreau, NM	
Mountainair Compressor Sta.	6-30-82	19420 gals.	38	5-21-80	Mountainair, NM	

17 25%

Total liquids containing 50 PPM to 500 PPM PCBs removed from PCB affected portion of system 36,678 gals.

Total liquids containing 500 PPM or greater PCBs removed from PCB affected portion of system -0-